



Consulting  
Engineers and  
Scientists

## Annual CCR Inspection Report

Mercer Generating Station, Hamilton Township, New Jersey

**Submitted to:**


PSEG Fossil LLC  
80 Park Plaza  
Newark, NJ 07101

**Submitted by:**

GEI Consultants, Inc.  
18000 Horizon Way, Suite 200  
Mt. Laurel, New Jersey 08054

October 16, 2018  
Project 1504710



  
Tyler K. Schott, P.E.  
Project Manager  
NJ PE #24GE04794800  
Date: 10/16/2018

## Table of Contents

---

<b>1.</b>	<b>Introduction</b>	<b>1</b>
1.1	Description of Impoundments	1
<b>2.</b>	<b>2017 Annual Inspection</b>	<b>2</b>
2.1	Annual Inspection	2
2.1.1	Review of Available Information	2
2.1.2	Visual Inspection of the CCR unit	2
2.1.3	Visual Inspection of Hydraulic Structures	2
<b>3.</b>	<b>Annual Inspection Report</b>	<b>3</b>
3.1	Changes in Geometry	3
3.2	Location and Type of Instrumentation	3
3.3	Depths and Elevations	3
3.4	Storage Capacity	3
3.5	Volumes	3
3.6	Structural Weakness	3
3.7	Other Notes Changes	3
3.8	Deficiency Identified	4

## Figures

---

1. Site Location Map
2. Site Plan
3. CCR Impoundment Footprint and Initial Conditions Plan

TKS/lzf

B:\Working\PSEG\1504710 CCR Support\07\_Reports\2018-10-15 Annual Inspection Reports\Mercer\2018-10-15 Mercer Facility Annual Inspection Report.docx

# 1. Introduction

---

On behalf of PSEG Fossil (PSEG), GEI Consultants, Inc. (GEI) has prepared the 2018 Annual Inspection Report for the Coal Combustion Residuals (CCR) Surface Impoundments<sup>1</sup> (Impoundments) at the Mercer Generating Station. There are two inactive Impoundments:

- North Fly Ash Pond; and
- South Fly Ash Pond.

This report was prepared to meet the requirements of 40 CFR 257.83.

## 1.1 Description of Impoundments

The Mercer Generating Station is owned by PSEG Power and located at 2512 Lamberton Road in Hamilton Township, New Jersey. The facility maintains 10-acre North Fly Ash Pond and a 6-acre South Fly Ash Pond that ceased receiving CCR prior to October 19, 2015. The impoundments are constructed as predominantly incised impoundments with a bermed wall along Lamberton Road that varies in height above the surrounding grade by five-to-six feet. A Notice of Intent (NOI) to initiate closure of the CCR impoundment under Section 257.100 of the CCR Rule was posted on the PSEG CCR Rule Compliance Data and Information website on November 6, 2015. Though closure by removal of all CCR is no longer permitted under Section 257.100 of the CCR, Closure of these CCR impoundments is proceeding in accordance with Section 257.102 of the CCR rule and the associated 547-day timeframe extension. As documented in a March 23, 2017 memo prepared by GEI, CCR removal was completed on October 19, 2016 and all CCR has been removed from the Impoundments.

---

<sup>1</sup> CCR Surface Impoundment is defined at 40 CFR 257.53.

## **2. 2018 Annual Inspection**

---

### **2.1 Annual Inspection**

As required by 40 CFR 257.83(b), inspections of all CCR surface impoundments were performed by a qualified professional engineer (Tyler K. Schott, NJ P.E. #24GE04794800) on multiple occasions. The October 19, 2016 inspection served as the initial inspection. As discussed above, the Impoundments are inactive and have been closed through removal of all CCR. The berms surrounding each Impoundment are still present and were inspected as part of the 2018 annual inspection conducted on August 3, 2018.

#### **2.1.1 *Review of Available Information***

In accordance with 257.83(b)(i), a review of available information regarding the status and condition of the CCR unit is required. There were no available design documents or impoundment testing data to perform a quantitative analysis of the berm condition. Based on the visual observations of the impoundments during inspections, and the inactive/closed status of the impoundments, quantitative evaluation of each impoundment was not necessary.

#### **2.1.2 *Visual Inspection of the CCR unit***

In accordance with 257.83(b)(ii), a visual inspection of the CCR unit to identify signs of distress or malfunction is required. The Impoundments are inactive and have been closed. Based on the visual inspections, the berms are in good condition and no signs of distress or malfunction was observed.

#### **2.1.3 *Visual Inspection of Hydraulic Structures***

In accordance with 257.83(b)(iii), a visual inspection of any hydraulic structures underlying the base of the CCR unit or passing through the dike of the CCR unit is required. The hydraulic control structures were inspected visually by facility personnel on a weekly basis and subject to frequent inspection by a licensed Professional Engineer. Throughout the process of closure by removal, the hydraulic control structures remained intact, structurally sound, and unused. Discharge from the Mercer facility impoundments would require a significant volume of water and positive action from facility personnel to initiate discharge.

### **3. Annual Inspection Report**

---

The following sections are required to be inspected and included in the inspection report as stated in 40 CFR 257.83(2).

#### **3.1 Changes in Geometry**

No changes in geometry were noted. The Impoundments have undergone closure by removal.

#### **3.2 Location and Type of Instrumentation**

Historically, there was no instrumentation used to evaluate the status and condition of the berms associated with facility CCR impoundments. Due to the closure of the Impoundments, no new instrumentation is required for monitoring.

#### **3.3 Depths and Elevations**

Evaluation of the minimum, maximum and present depth and elevation of the impounded water is required as part of the inspection report. The CCR has been fully removed and therefore this portion of the annual inspection is not applicable.

#### **3.4 Storage Capacity**

The Impoundments have undergone closure and therefore have no storage capacity available for CCR.

#### **3.5 Volumes**

The CCR has been fully removed and therefore this portion of the annual inspection is not applicable.

#### **3.6 Structural Weakness**

The Impoundments have undergone closure. The berms surrounding the Impoundments remain unchanged. There were no observed structural weaknesses in the Impoundments.

#### **3.7 Other Noted Changes**


As discussed throughout, the Impoundments are closed. Many of the inspection items required by 40 CFR 257.83(2) and discussed above are not applicable as the CCR has been removed.

### **3.8 Deficiency Identified**

No deficiencies were observed as part of the annual inspection activities for the Impoundments.

## Figures

---



**SOURCE:**

1. USGS TOPOGRAPHIC MAP ACCESSED  
VIA ARCGISONLINE.COM

0 2,000 4,000



SCALE: 1" = 2000'

Annual CCR Inspection Report  
PSEG - Mercer  
Hamilton, New Jersey

PSEG Power, LLC  
New Jersey



Project 1504710


SITE LOCATION MAP

August 2017


Fig. 1




**LEGEND:**

 Approximate Property Line

<p><b>SOURCE:</b> 1. AERIAL FROM ESRI WORLD IMAGERY - 2015.</p>	<div><div><div>0</div><div>400</div><div>800</div></div><div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div><div>SCALE: 1" = 400'</div></div>	Annual CCR Inspection Report PSEG - Mercer Hamilton, New Jersey		<div><div>GEI</div><div>Consultants</div></div>	SITE PLAN	
		PSEG Power, LLC New Jersey			Project 1504710	October 2018





Consulting  
Engineers and  
Scientists

## Annual CCR Inspection Report

Mercer Generating Station, Mercer, New Jersey

**Submitted to:**

PSEG Fossil LLC  
80 Park Plaza  
Newark, NJ 07101

**Submitted by:**

GEI Consultants, Inc.  
18000 Horizon Way, Suite 200  
Mt. Laurel, New Jersey 08054

October 27, 2017

Project 1504710



  
Tyler K. Schott, P.E.  
Project Manager  
NJ PE #24GE04794800  
Date: October 27, 2017

## Table of Contents

---

<b>1.</b>	<b>Introduction</b>	<b>1</b>
1.1	Description of Impoundments	1
<b>2.</b>	<b>2017 Annual Inspection</b>	<b>2</b>
2.1	Annual Inspection	2
2.1.1	Review of Available Information	2
2.1.2	Visual Inspection of the CCR unit	2
2.1.3	Visual Inspection of Hydraulic Structures	2
<b>3.</b>	<b>Annual Inspection Report</b>	<b>3</b>
3.1	Changes in Geometry	3
3.2	Location and Type of Instrumentation	3
3.3	Depths and Elevations	3
3.4	Storage Capacity	3
3.5	Volumes	3
3.6	Structural Weakness	3
3.7	Other Notes Changes	3
3.8	Deficiency Identified	4

## Figures

---

1. Site Location Map
2. Site Plan
3. CCR Impoundment Footprint and Initial Conditions Plan

TKS/lrf

H:\WPROC\Project\PSEG\Mercer\Mercer Facility Annual Inspection Report - Final 10-27-2017.docx

# 1. Introduction

---

On behalf of PSEG Fossil (PSEG), GEI Consultants, Inc. (GEI) has prepared the 2017 Annual Inspection Report for the Coal Combustion Residuals (CCR) Surface Impoundments<sup>1</sup> (Impoundments) at the Mercer Generating Station. There are two inactive Impoundments:

- North Fly Ash Pond; and
- South Fly Ash Pond.

This report was prepared to meet the requirements of 40 CFR 257.83.

## 1.1 Description of Impoundments

The Mercer Generating Station is owned by PSEG Power and located at 2512 Lamberton Road in Hamilton Township, New Jersey. The facility maintains 10-acre North Fly Ash Pond and a 6-acre South Fly Ash Pond that ceased receiving CCR prior to October 19, 2015. The impoundments are constructed as predominantly incised impoundments with a bermed wall along Lamberton Road that varies in height above the surrounding grade by five-to-six feet. A Notice of Intent (NOI) to initiate closure of the CCR impoundment under Section 257.100 of the CCR Rule was posted on the PSEG CCR Rule Compliance Data and Information website on November 6, 2015. Though closure by removal of all CCR is no longer permitted under Section 257.100 of the CCR, Closure of these CCR impoundments is proceeding in accordance with Section 257.102 of the CCR rule and the associated 547-day timeframe extension. As documented in a March 23, 2017 memo prepared by GEI, CCR removal was completed on October 19, 2016 and all CCR has been removed from the Impoundments.

---

<sup>1</sup> CCR Surface Impoundment is defined at 40 CFR 257.53.

## **2. 2017 Annual Inspection**

---

### **2.1 Annual Inspection**

As required by 40 CFR 257.83(b), inspections of all CCR surface impoundments were performed by a qualified professional engineer (Tyler K. Schott, NJ P.E. #24GE04794800) on multiple occasions. The October 19, 2016 inspection served as the annual inspection event for this impoundment. In accordance with the CCR Rule, weekly inspections were initiated in April 2017 and are ongoing. The weekly inspections confirm that there is no change to the Impoundments since the October 19, 2016 annual inspection. As discussed above, the Impoundments are inactive and have been closed through removal of all CCR. The berms surrounding each Impoundment are still present and were inspected as part of the annual inspection.

#### **2.1.1 Review of Available Information**

In accordance with 257.83(b)(i), a review of available information regarding the status and condition of the CCR unit is required. There were no available design documents or impoundment testing data to perform a quantitative analysis of the berm condition. Based on the visual observations of the impoundments during inspections, and the inactive/closed status of the impoundments, quantitative evaluation of each impoundment was not necessary.

#### **2.1.2 Visual Inspection of the CCR unit**

In accordance with 257.83(b)(ii), a visual inspection of the CCR unit to identify signs of distress or malfunction is required. The Impoundments are inactive and have been closed. Based on the visual inspections, the berms are in good condition and no signs of distress or malfunction was observed.

#### **2.1.3 Visual Inspection of Hydraulic Structures**

In accordance with 257.83(b)(iii), a visual inspection of any hydraulic structures underlying the base of the CCR unit or passing through the dike of the CCR unit is required. The hydraulic control structures were inspected visually by facility personnel on a weekly basis and subject to frequent inspection by a licensed Professional Engineer. Throughout the process of closure by removal, the hydraulic control structures remained intact, structurally sound, and unused. Discharge from the Mercer facility impoundments requires significant volumes of water to accumulate in the impoundments and positive action from facility personnel to initiate discharge.

### **3. Annual Inspection Report**

---

The following sections are required to be inspected and included in the inspection report as stated in 40 CFR 257.83(2).

#### **3.1 Changes in Geometry**

No changes in geometry were noted. The Impoundments have undergone closure by removal.

#### **3.2 Location and Type of Instrumentation**

Historically, there was no instrumentation used to evaluate the status and condition of the berms associated with facility CCR impoundments. Due to the closure of the Impoundments, no new instrumentation is required for monitoring.

#### **3.3 Depths and Elevations**

Evaluation of the minimum, maximum and present depth and elevation of the impounded water is required as part of the inspection report. The CCR has been fully removed and therefore this portion of the annual inspection is not applicable.

#### **3.4 Storage Capacity**

The Impoundments have undergone closure and therefore have no storage capacity available for CCR.

#### **3.5 Volumes**

The CCR has been fully removed and therefore this portion of the annual inspection is not applicable.

#### **3.6 Structural Weakness**

The Impoundments have undergone closure. The berms surrounding the Impoundments remain unchanged. There were no observed structural weaknesses in the Impoundments.

#### **3.7 Other Notes Changes**


As discussed throughout, the Impoundments are closed. Many of the inspection items are not applicable as the CCR has been removed.

### **3.8 Deficiency Identified**

No deficiencies were observed as part of the annual inspection activities for the Impoundments.

## Figures

---



**SOURCE:**

1. USGS TOPOGRAPHIC MAP ACCESSED  
VIA ARCGISONLINE.COM

0 2,000 4,000



SCALE: 1" = 2000'

Annual CCR Inspection Report  
PSEG - Mercer  
Hamilton, New Jersey

PSEG Power, LLC  
New Jersey



Project 1504710

SITE LOCATION MAP

August 2017

Fig. 1



**SOURCE:**  
1. AERIAL FROM ESRI WORLD IMAGERY - 2015.

0 400 800  
SCALE: 1" = 400'

Annual CCR Inspection Report  
PSEG - Mercer  
Hamilton, New Jersey

PSEG Power, LLC  
New Jersey




Project 1504710

SITE PLAN


October 2017

Fig. 2



- LEGEND**
- ▲ BM-1 SURVEY CONTROL MONUMENT
  - PL — PROPERTY LINE (APPROXIMATE)
  - 50 — EXISTING GROUND SURFACE CONTOUR
  - ROAD — ROAD
  - x — x — FENCE
  - BUILDINGS — BUILDINGS
  - PIPE — PIPE
  - TOWER — ELECTRIC TOWER
  - RAILROAD TRACKS — RAILROAD TRACKS
  - OH — OVERHEAD ELECTRIC
  - 10 — PROPOSED EXCAVATION CONTOUR

- NOTES:**
1. HORIZONTAL DATUM BASED ON NEW JERSEY STATE PLANE COORDINATES, NAD 83.
  2. VERTICAL DATUM BASED ON NAVD 88.
  3. SITE CONTOURS BASED ON USGS LIDAR SURVEY FROM APRIL 2009. THE DATA WAS OBTAINED FROM THE NEW JERSEY OFFICE OF INFORMATION TECHNOLOGY, OFFICE OF GEOGRAPHIC INFORMATION SYSTEMS.



<p>Annual CCR Inspection Report PSEG - Mercer Hamilton, New Jersey PSEG Power, LLC New Jersey</p>	<div data-bbox="2548 1860 2701 1952"></div> <div data-bbox="2701 1860 2990 1952"><p>CCR IMPOUNDMENT FOOTPRINT AND INITIAL CONDITIONS PLAN - NORTH AND SOUTH FLY ASH PONDS</p></div> <div data-bbox="2548 1952 2990 1992"><p>Project 1504710    October 2017    Fig. 3</p></div>
---	---